

{youtube}Vmnux8Z8B8U{/youtube}

Armoured cable or SWA (steel wired armoured) cable is the accepted, standard for underground use. This cable can be used in many industrial and commercial applications where its steel armor is required.

Conductor

Stranded bare copper/ Tinned copper

Insulation

Cross-linked Polyethylene (XLPE) or PVC or LSHF (Halogen free)

Armor

Galvanized steel armor

Jacket

PVC Jacket

Temperature

105 Degrees C

Voltage

300V/450V/750V/1000V

Standards

British Standard BS6724 or BS5467

Maximum

32mm

